



DATE 2015-10-30	TECHNICIAN Darren Mann	JOB/ORDER # 5455	REFERENCE TEXT Client reference
FIRST NAME Naomi		LAST NAME Vidal	
BILLING ADDRESS COMPANY / BILLING NAME #2009 - 668 CITADEL PARADE VANCOUVER, V6B1W6 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #2009 - 668 CITADEL PARADE, BUZZER 6171 VANCOUVER, V6B1W6 BRITISH COLUMBIA, CANADA	
PHONE 604.341.5814		EMAIL naomividal@shaw.ca	

REASON FOR TODAY'S CALL:  
 bath tub faucet is leaking when one is taking a shower. Also the garborator is not working.

DESCRIPTION OF WORK PERFORMED:  
 -I replaced the tub spout with a new Delta pull down type. -I unjammed the garburator and tested by filling and draining the sink while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Standard Tub Spout Diverter	\$149.00	\$149.00
SUBTOTAL:				\$149.00
GST (5%):				\$7.45
TOTAL:				\$156.45

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

**WARRANTY:** **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY  
**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

*M Vidal*  
 \_\_\_\_\_  
 CUSTOMER SIGNATURE

2015-10-30  
 \_\_\_\_\_  
 DATE