



HST #837181627

DATE 2015-11-26	TECHNICIAN Darren Mann		JOB/O 5560	RDER #	REFERENCE TEXT Client reference
FIRST NAME John		LAST NAME St Germain			
BILLING ADDRESS COMPANY / BILLING NAME 27 ALEXANDER ST VANCOUVER, V6A1B2 BRITISH COLUMBIA, CANADA		9	4	SERVICE ADDRESS 201 - 27 ALEXANDER ST VANCOUVER, V6A1B2 BRITISH COLUMBIA, CANADA	
PHONE 6042192944				EMAIL Jstgermain123@gmail.com	

REASON FOR TODAY'S CALL:

Bath tub spout leaks when shower is on. New diverter didn't help

DESCRIPTION OF WORK PERFORMED:

I replaced the tub spout and tested.

QTY.	CODE	DESCRIPTION				PRICE
1	y	Replace Standard Tub Spout Diverter				\$159.00
		VARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$159.00	
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.95	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$166.95	
			THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND			

<u> Thank You!</u>

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CHARGES, E. & O. E.

2015-11-26 CUSTOMER SIGNATURE DATE