



HST #837181627

DATE 2016-01-12	TECHNICIAN Darren Mann		JOB/ORDER # 5730		REFERENCE TEXT Client reference	
FIRST NAME Mark		LAST NAME Williams				
BILLING ADDRESS CENTURY 21 PRUDENTIAL ESTATES (RMD) LTD 7320 WESTMINSTER HWY RICHMOND, V6X1A1 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS  403 - 1001 RICHARDS ST DAL PRIHAR(TENANT): 604.655.5414 604.318.0283 RICHMOND, BRITISH COLUMBIA, CANADA		
PHONE 604.817.2080				EMAIL mw@century21pel.com		

REASON FOR TODAY'S CALL:

Shower handle broken

## DESCRIPTION OF WORK PERFORMED:

The shower valve cartridge broke off at the stem. I replaced the mixing and pressure balance cartridges and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Mixing & Pressure Balance Cartridges HC44	\$189.00	\$189.00
Please visit our feedback page at:  www.yaletownplumbing.com/feedback  Fill in the required details from your invoice and tell us how we did.  Thank Youl		WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$189.00
		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$9.45
			TOTAL:	\$198.45
		WE did.  MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND  MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,  SETTLED RUSTED DETERIORATION OR LEAD PIPES FIXTURES CLEAN QUITS AND ANY OTHER DAMAGES.		

CUSTOMER SIGNATURE

DATE