

2016-03-17

DATE

HST #837181627

DATE 2016-03-17	TECHNICIAN Darren Mann		JOB/ORDER # 5958	REFERENCE TEXT
FIRST NAME Advent		LAST NAME Admin		·
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 409 - 555 ABBOTT ST 604.376.8523 HOME 604.729.8523 VANCOUVER, BRITISH COLUMBIA, 0	
PHONE 604.736.6478	1=		EMAIL andrea@adventvancou	ıver.com

REASON FOR TODAY'S CALL:

Leak coming from area by washer dryer.

DESCRIPTION OF WORK PERFORMED:

The tenant mentioned while onsite that the restoration company had determined that the moisture was accumulating around the cast iron drain stack and that they would have to contact the plumber that deals with the building to take care of it. I visually inspected the area and could see that the drain stack was covered in rust staining and moisture was collecting around the base. I did not see any sign of moisture coming from the water supply or drain piping coming to or from the laundry

QTY.	CODE	DESCRIPTION		PRICE
0.5	11	Discount Labour	\$99.00	\$49.50
0	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			\$49.50
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback Fill in the required details from your invoice and tell us how we did. Thank You!		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$2.48
		s from your	TOTAL:	\$51.98
		MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,		

CUSTOMER SIGNATURE