

Phone: 604.727.4484 yaletownplumbing.com



HST #837181627

DATE 2016-04-22	TECHNICIAN Darren Mann		JOB/ORDER # 6068		REFERENCE TEXT Client reference
FIRST NAME Stevi		LAST NAME Davis			
BILLING ADDRESS COMPANY / BILLING NAME 139 DRAKE ST VANCOUVER, V6Z 2T8 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 16A - 139 DRAKE ST LEONARD(HUSBAND): 604.78: BUZZER: 862 VANCOUVER, V6Z 2T8 BRITISH COLUMBIA, CANADA	
PHONE 6047298297				EMAIL stevi.davis@gmail.com	

REASON FOR TODAY'S CALL:

Several problems: biggest problem is that now our kitchen sink is clogged, and dishwasher won't drain. Also, both toilets have to have the handle jiggled to stop the water from running. AND our guest bath when you turn on the shower, only half the water goes to the shower head and the other half keeps draining from the tub tap. HELP! *call husband to gain access to unit

DESCRIPTION OF WORK PERFORMED:

-The kitchen sink drain was cleared by a handyman before our visit and was flowing freely. -The garburator grinding chamber was deteriorated to the point that metal was flaking off creating holes that larger pieces of food could fit through. I replaced the garburator with a new a Waste King 1001 and tested by filling and draining the sink while running the garburator. -The dishwasher had standing water in it, I ran the dishwasher through a short fill & drain cycle which drained the standing water. Both toilets are original to the building and I would suggest replacing them over repairing them. -The guest bathroom tub spout is not fully diverting water. To repair the spout would require ordering parts from Kohler which would take 5-7 weeks to arrive. The cost of the repair would be similar to replacing the spout with a new Delta Pull-down type spout.

TECHNICIAN RECOMMENDATIONS:

Toilet measurements that will be required when shopping for new toilets: (GUEST BATHROOM: 31"to underside of countertop 12" rough-in, elongated) (MASTER BATHROOM: 31" to underside of countertop, 11-1/4" rough-in, elongated)

QTY.	CODE		UNIT PRICE	PRICE	
1		Supply & Install 1/2HP Wa	\$279.00	\$279.00	
		warrar	ITY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$279.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO		\$13.95
		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. EST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$292.95
			THAT CERVICES LICTED AROVE ARE CATICEACTORY COMPLETED AND THAT CHARGES AND		

Thank You!

MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CHARGES. E. & O. E

2016-04-22

CUSTOMER SIGNATURE

DATE