



HST #837181627

DATE 2016-04-26	TECHNICIAN Darren Mann		JOB/ORDER # 6101	REFERENCE TEXT 16-0571
FIRST NAME Advent		LAST NAME Admin		
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 3103 - 1438 RICHARDS ST BUZ#1220 DEVIN: 778.877.7526 ANTHONY: WRONG NUMBER VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.736.6478	/ = <		EMAIL andrea@adventvanco	puver.com

REASON FOR TODAY'S CALL:

-kitchen faucet leaking

DESCRIPTION OF WORK PERFORMED:

-The kitchen faucet was leaking internally and could not be repaired. I replaced the faucet with a new Delta Palo.

TECHNICIAN RECOMMENDATIONS:

**During testing I noticed cracks starting to develope in the garburator housing, this should be replaced before the cracks worsen and start to leak water to the cabinet below.

outsing below.				
QTY.	CODE	DESCRIPTION		PRICE
1	116	Delta Palo CP - Pull-Out INSTALLED	\$329.00	\$329.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			SUBTOTAL:	\$329.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$16.45
			TOTAL:	\$345.45
		we did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLE PROPERTY PETERDATION OF LAD DIFFE STAT		

CUSTOMER SIGNATURE