

(SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2016-07-04	TECHNICIAN Darren Mann		JOB/O 6294	RDER #	REFERENCE TEXT Client reference
FIRST NAME Emmy		LAST NAME Pang	7		
BILLING ADDRESS COMPANY / BILLING NAME 1205 - 1255 SEYMOUR ST VANCOUVER, V6B0H1 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 1205 - 1255 SEYMOUR ST VANCOUVER, V6B0H1 BRITISH COLUMBIA, CANADA	
PHONE 604.448.9996				EMAIL abc.realty@hotmail.com	

REASON FOR TODAY'S CALL: tub/shower diverter not working.

DESCRIPTION OF WORK PERFORMED:

I replaced the tub spout with a new Delta pull-down type diverter spout and tested.

QTY.	CODE		UNIT PRICE	PRICE		
1		Replace Standard Tub Spout Diverter				\$159.00
0		warranty:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$159.00
Give us Feedback Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 3 MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE		GST (5%):	\$7.95
		com/feedback [1]	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		TOTAL:	\$166.95
<u>Tha</u>	<u>rk Yoi</u>	SETTLED, RESULTIN TERMS: N CHARGES	RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND A 3 FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. ET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS E. & O. E.			
			CUSTOMER SIGNATURE	DATE		