

## HST #837181627

DATE 2016-07-07			JOB/ORDER # 6309		REFERENCE TEXT Client reference
FIRST NAME Benjamin		LAST NAME Yu	7		
BILLING ADDRESS GKY DESIGNS 2770 NADINA DRIVE COQUITLAM, V3C6A5 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 1704 - 499 BROUGHTON ST, B REBECCA(TENAT): 778.710.18 COQUITLAM, V6G 3K1 BRITISH COLUMBIA, CANADA	327
PHONE 604.368.0808				EMAIL byu777@gmail.com	

REASON FOR TODAY'S CALL:

Master bedroom toilet keeps filling after flush for 15 mins. It seems to need a special part from the concierge. \*housekeeper will be home.

## DESCRIPTION OF WORK PERFORMED:

I replaced the membrane and discharge piston in the ensuite bathroom toilets do tested by flushing multiple times.

<b>QTY</b> .	CODE			DESCRIPTION	UNIT PRICE	PRICE	
1	/	Replace Discharge	ace Discharge Piston & Membrane - Porcher				\$159.00
0		and a du	WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$159.00
Give us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTE MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT M.		GST (5%):	\$7.95	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$166.95		
		MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TEMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E. 2016-07-07					
				CUSTOMER SIGNATURE	DATE		