

2016-09-16

HST #837181627

DATE 2016-09-16	TECHNICIAN Darren Mann		JOB/ORDER # 6517	REFERENCE TEXT Client reference				
FIRST NAME Easyrent		LAST NAME Admin						
BILLING ADDRESS EASYRENT REAL ESTATE SERVICES LTD. 100 - 1290 HOMER ST VANCOUVER, V6B2Y5 BRITISH COLUMBIA, CANADA			SERVICE ADDRES 2505 - 1189 MELV LAUREN: 778.822. VANCOUVER, BRITISH COLUMB	ILLE ST 9460				
PHONE 604.662.3279		EMAIL info@easyrent.ca						

## REASON FOR TODAY'S CALL:

Water rises high in bowl when flushed then slowly drains through.

## DESCRIPTION OF WORK PERFORMED:

-I ran the 6' toilet auger through the toilet and cleared the blockage. Tested by flushing large rolled up balls of toilet paper. -During testing I noticed the toilet tank fills very slowly and the bowl is not sufficiently filled after each flush, the flapper was also starting to warp. I replaced the toilet FillValve, flapper, and supply line and tested.

QTY.	CODE	DESCRIPTION			PRICE
1	//,	Replace Toilet FillVal	ve, Flapper, Supply - Standard	\$169.00	\$169.00
<b>L</b> mo	, 115 J	eedlack w	ARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$169.00
Gwe us Feedback  Please visit our feedback page at:  www.yaletownplumbing.com/feedback  Fill in the required details from your invoice and tell us how we did.  Thank You!			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$8.45
		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.  INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY		\$177.45
		we did.	MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE