

HST #837181627

DATE 2016-11-07			JOB/O 6690	RDER #	REFERENCE TEXT 16-1447
FIRST NAME Advent		LAST NAME Admin	7		
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA		19	4	SERVICE ADDRESS 907 - 1028 BARCLAY ST KEYS AT ADVENT VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.736.6478				EMAIL andrea@adventvancouver.com	

REASON FOR TODAY'S CALL:

Tub/shower diverter not working

DESCRIPTION OF WORK PERFORMED:

-The tub/shower diverter handle fell off due to the set screw becoming loose. I resecured the handle by tightening the set screw and applied a small amount of crazy glue to the handle to help mitigate the chances of it working itself loose again in the future.

QTY.	CODE		UNIT PRICE	PRICE	
1		Discount Labour		\$99.00	\$99.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		war	RRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$99.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$4.95
		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$103.95
		M S R	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		
			CUSTOMER SIGNATURE DATE		