



HST #837181627

UNIT PRICE

DATE 2016-11-15	TECHNICIAN		JOB/ORDER # 6709	REFERENCE TEXT 16-1482
FIRST NAME Advent		LAST NAME Admin		
BILLING ADDRESS ADVENT REAL ESTATE SERV #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA			SERVICE ADDRES 709 - 756 GREAT KEYS AT OFFICE VANCOUVER, BRITISH COLUME	NORTHERN WAY ACCESS CODE16047274484
PHONE 604.736.6478			EMAIL andrea@adventva	ncouver.com

REASON FOR TODAY'S CALL:

Toilet: seal between the tank and the bowl of the toilet not operating properly, specifically when flushing.

DESCRIPTION OF WORK PERFORMED:

CODE

The tank to bowl gasket was leaking and the FillValve was spraying out of the top. I replaced the FillValve, supply line, tank to bowl gasket, and tank bolts. Tested and in good working order.

DESCRIPTION

		5233		
1		Discount Labour	\$99.00	\$99.00
1	2121352	B1-16DL 3/8X20 SPEEDI+ WC CONN	\$11.00	\$11.00
1	9520164	PRO45B ANTI-SYPH FILL VLV UQ	\$35.00	\$35.00
1		Tank To Bowl Gasket & Bolts	\$20.00	\$20.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			SUBTOTAL:	\$165.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$8.25
			TOTAL:	\$173.25

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

CUSTOMER SIGNATURE