



DATE 2016-12-01	TECHNICIAN Darren Mann	JOB/ORDER # 6767	REFERENCE TEXT Client reference
FIRST NAME Tom		LAST NAME Hawkins	
BILLING ADDRESS COMPANY / BILLING NAME #708 - 1295 RICHARDS ST VANCOUVER, BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #2605 - 1255 SEYMOUR ST BUZ#966 MICHELLE: 778.554.0880 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.889.5732		EMAIL hawkins@bernardllp.ca	

REASON FOR TODAY'S CALL:
 -Tub/shower diverter not working. -Shower head has come apart.

DESCRIPTION OF WORK PERFORMED:
 -The tub spout diverter was broken, i replaced the tub spout with a new Delta pull-down type diverter spout and tested. -The shower head had come apart, i was able to re-assemble it and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Standard Tub Spout Diverter	\$159.00	\$159.00
			SUBTOTAL:	\$159.00
			GST (5%):	\$7.95
			TOTAL:	\$166.95

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

_____ 2016-12-01

 CUSTOMER SIGNATURE DATE