



HST #837181627

DATE 2017-01-04	TECHNICIAN Darren Mann		JOB/ORDER # 6858		REFERENCE TEXT Client reference
FIRST NAME Mark		LAST NAME Williams	7		
BILLING ADDRESS CENTURY 21 PRUDENTIAL ES 7320 WESTMINSTER HWY RICHMOND, V6X1A1 BRITISH COLUMBIA, CANADA	, ,	<u> </u>	4	SERVICE ADDRESS  609 - 1618 QUEBEC ST, BUZ#8 MIN(TENANT): 778.846.8881 RICHMOND, BRITISH COLUMBIA, CANADA	
PHONE 604.817.2080				EMAIL mw@century21pel.com	

## REASON FOR TODAY'S CALL:

install new kitchen faucet spray hose.

## DESCRIPTION OF WORK PERFORMED:

-I installed the new kitchen faucet spray hose and tested.-While onsite the tenant mentioned that the drainage on the left sink leaks periodically. I found the tailpiece to be cut too short, allowing the drainage to disconnect itself from the basket strainer assembly. I installed a longer brass tailpiece, re-connected the drainage, and tested by filling and draining both sides of the sink.

QTY.	CODE	DESCRIPTION		UNIT PRICE	PRICE
1	//,	Labour		\$109.00	\$109.00
1		Brass Tailpiece 6"		\$10.00	\$10.00
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your		warranty:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY  LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	SUBTOTAL:	\$119.00
				GST (5%):	\$5.95
		s from your		TOTAL:	\$124.95

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOW MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND TH MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESTITLED, RUSTED, DETERIORATION, OR LEAD PIPPS, FIXTURES, CLEAN OUTS A RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.	HAT CHARGES AND PONSIBLE FOR BROKEN,
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATE CHARGES. E. & O. E.	ERIALS AND TRUCK
	2017-01-04
CUSTOMER SIGNATURE	DATE