

HST #837181627

DATE 2017-01-24	TECHNICIAN Darren Mann		JOB/ORDER # 6929		REFERENCE TEXT Client reference
FIRST NAME Valerie		LAST NAME Porter			
BILLING ADDRESS COMPANY / BILLING NAME 2025 WEST 2ND AVE. VANCOUVER, V6J 1J6 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS #316 - 2025 WEST 2ND AVE., E VANCOUVER, V6J 1J6 BRITISH COLUMBIA, CANADA	
PHONE 604-733-7013				EMAIL vporter222@gmail.com	

REASON FOR TODAY'S CALL:

My toilet sometimes runs a bit after flushing, but stops after a minute or two. I noticed that the flapper is falling apart and needs to be replaced. I think the toilet is a Toto Dartmouth Eco (1.6gpf) model CST754E. The flapper may be a THU499S. The flush valve with flapper & nut may be a THU129P-3A.

DESCRIPTION OF WORK PERFORMED:

I replaced the toilet fillvalve, flapper, and supply line

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	//	Replace FillValve, Flapper, Supply Line - TOTO	\$199.00	\$199.00
<u>Q</u> me	s G	eedback warranty: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$199.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		k page at: Labour - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$9.95
			TOTAL:	\$208.95
		INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY WE did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGE	S	

Value Porter 2017-01-24 CUSTOMER SIGNATURE DATE