

DATE 2017-04-13	TECHNICIAN Darren Mann	JOB/ORDER # 7207	REFERENCE TEXT Client reference
FIRST NAME Evan	LAST NAME Deakin		
BILLING ADDRESS COMPANY / BILLING NAME 403 - 499 BROUGHTON ST VANCOUVER, V6G 3K1 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 403 - 499 BROUGHTON ST BUZZER: #1209 VANCOUVER, V6G 3K1 BRITISH COLUMBIA, CANADA	
PHONE 778-885-5060	EMAIL deakin@me.com		

REASON FOR TODAY'S CALL:

As per tel conversation with Darren, Kohler toilet tank fill mechanism won't fill tank and constantly makes a loud hissing noise. Master bathroom.

DESCRIPTION OF WORK PERFORMED:

I replaced the discharge piston and fillvalve membrane in the Ensuite Porcher toilet. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Discharge Piston & Membrane - Porcher	\$159.00	\$159.00


Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:		\$159.00
GST (5%):		\$7.95
TOTAL:		\$166.95

 _____ CUSTOMER SIGNATURE	2017-04-13 _____ DATE
---	-----------------------------