



HST #837181627

DATE 2017-05-12	TECHNICIAN Darren Mann		JOB/O 7284	RDER #	REFERENCE TEXT Client reference		
FIRST NAME Vera		LAST NAME Sal					
BILLING ADDRESS RENT IT FURNISHED 110 - 1020 MAINLAND STREET VANCOUVER, V6B 2T4 BRITISH COLUMBIA, CANADA		9	4	SERVICE ADDRESS  408 - 1275 HAMILTON ST SUSAN: 1.250.889.5171 VANCOUVER, BRITISH COLUMBIA, CANADA			
PHONE 778.980.9100				EMAIL vera@rentitfurnished.com			

REASON FOR TODAY'S CALL: lavatory faucet loose and leaking

## DESCRIPTION OF WORK PERFORMED:

-I resecured the lavatory faucet to the countertop by tightening the nut that secures it. -The faucet was leaking through the stem of the cartridge onto the countertop. I replaced the cartridge(K35B) and tested. During testing I noticed the aerator was spraying out of the sides. I replaced the aerator and tested again. Faucet is secure and in good working order.

QTY.	CODE		DESCRIPTION	UNIT PRICE	PRICE
1	//	Replace Lav Faucet Single Lever Cartridge - Standard			\$159.00
1		Faucet Aearator	3	\$10.00	\$10.00
www.yaletownplumbing.com/feedback [1] Fill in the required details from your		ITY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$169.00	
			<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO		\$8.45
		s from your			\$177.45

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

	2017-05-12
CUSTOMER SIGNATURE	DATE