

(B) @SimplyPlumbing | | YaletownPlumbing

2017-05-24

HST #837181627

DATE 2017-05-24	TECHNICIAN Darren Mann		JOB/ORDER # 7321		REFERENCE TEXT Client reference				
FIRST NAME Anthony		LAST NAME Perl							
BILLING ADDRESS COMPANY / BILLING NAME 499 BROUGHTON ST VANCOUVER, V6G3K1 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 302 - 499 BROUGHTON ST BUZZER: #1204 VANCOUVER, V6G3K1 BRITISH COLUMBIA, CANADA					
PHONE 778.371.9568				EMAIL aperl@sfu.ca					

REASON FOR TODAY'S CALL:

Slow leak on under-sink water filter in kitchen.

DESCRIPTION OF WORK PERFORMED:

-The leak seemed to be coming from between the water filter housing and the bracket it attaches to. This leak worsened when the water supply valve was turned off. I added Teflon tape to the threads of the filter bracket and reinstalled the filter and housing. Tested and no leaks present. -The master toilet flapper was sticking in the

open position	n on some flus	snes. I found the lever	to be catching. I adjusted the lever and tested.		
QTY.	CODE	DESCRIPTION			PRICE
1	//.	Labour		\$109.00	\$109.00
Q	Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				\$109.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$5.45
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$114.45
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE