

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2017-05-24	TECHNICIAN Darren Mann		JOB/O 7324	RDER #	REFERENCE TEXT Client reference
FIRST NAME Easyrent		LAST NAME Admin	7		
BILLING ADDRESS EASYRENT REAL ESTATE SE 100 - 1290 HOMER ST VANCOUVER, V6B2Y5 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 2904 - 888 HOMER ST BUZ#10 SUNNY: 604.617.1891 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.662.3279				EMAIL info@easyrent.ca	

REASON FOR TODAY'S CALL: Tub/shower diverter broken

## DESCRIPTION OF WORK PERFORMED:

The tub/shower diverter knob came loose and fell off. I removed the trim and handle, reattached the diverter knob, and reinstalled the trim & handle. During testing I noticed the tub was draining very slowly. I used the PowerSpin drain snake to clear a large amount of hair from the drain.

QTY.	CODE	DESCRIPTION				UNIT PRICE	PRICE
1		Discount Labour	×			\$99.00	\$99.00
Guve us Geedback Please visit our feedback page at:   www.yaletownplumbing.com/feedback [1]   Fill in the required details from your invoice and tell us how we did.   Thank Youl Image: State of the state of t		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS. THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREB		SUBTOTAL:	\$99.00	
				MADE, ABSOLUTELY NO	GST (5%):	\$4.95	
		INTEREST A			TOTAL:	\$103.95	
		MATERIALS SETTLED, RU RESULTING	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPC USTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AN FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. : CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERI E. & O. E.				
				CUSTOMER SIGNATURE	DATE		