



DATE 2017-05-26	TECHNICIAN Darren Mann	JOB/ORDER # 7313	REFERENCE TEXT Client reference
FIRST NAME Laura		LAST NAME Simpson	
BILLING ADDRESS COMPANY / BILLING NAME 701 - 1188 QUEBEC ST VANCOUVER, V6A4B2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 701 - 1188 QUEBEC ST, BUZZER 7300 VANCOUVER, V6A4B2 BRITISH COLUMBIA, CANADA	
PHONE 604.377.8914		EMAIL laurasimps@gmail.com	

REASON FOR TODAY'S CALL:
Master Ensuite shower only getting Luke warm handle stiff to turn.


DESCRIPTION OF WORK PERFORMED:
I replaced the mixing & pressure balance cartridge within the Ensuite shower valve and tested. The temperature now gets as hot as the Lav faucet.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Shower Cartridge - Temp II	\$209.00	\$209.00
SUBTOTAL:			\$209.00	\$209.00
GST (5%):			\$10.45	\$10.45
TOTAL:			\$219.45	\$219.45

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY
LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



 CUSTOMER SIGNATURE

2017-05-26

 DATE