

HST #837181627

DATE 2017-05-31	TECHNICIAN Darren Mann		JOB/ORDER # 7342	REFERENCE TEXT Client reference	
FIRST NAME Fern		LAST NAME Jeffries			
BILLING ADDRESS COMPANY / BILLING NAME TH1 - 63 KEEFER PLACE BUZ#7097 VANCOUVER, V6B 6N6 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS TH1 - 63 KEEFER PLACE BUZ#7097 VANCOUVER, V6B 6N6 BRITISH COLUMBIA, CANADA		
PHONE 604.732.7097			EMAIL fern@me.com		

REASON FOR TODAY'S CALL:

I believe the problem is the diverter in my shower. The water flows through the faucet, but will not be diverted into the shower head. This is an American Standard set. Can the diverter be replaced/fixed?

DESCRIPTION OF WORK PERFORMED:

I replaced the faulty tub spout with a new Delta pull-down type diverter spout. During testing I noticed the shower head was broken as well. I replaced the shower head with a standard Delta head.

QIY.	CODE	DESCRIPTION		PRICE
1		Replace Standard Tub Spout Diverter	\$159.00	\$159.00
1		Delta Shower Head & Arm	\$25.00	\$25.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			SUBTOTAL:	\$184.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$9.20
			TOTAL:	\$193.20

Thank You!

invoice and tell us how we did.

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2017-05-31

CUSTOMER SIGNATURE

DATE