

(B) @SimplyPlumbing | YaletownPlumbing

HST #837181627

DATE 2017-06-02	TECHNICIAN Darren Mann		JOB/ORDER # 7380	REFERENCE TEXT	
FIRST NAME Vera		LAST NAME Salomatina			
BILLING ADDRESS ILVER INVESTMENTS LTD 2108 - 1010 RICHARDS ST VANCOUVER, V6B1G2 BRITISH COLUMBIA, CANADA		1132 - 933 HORNB PAUL: 604.802.133 VANCOUVER,	SERVICE ADDRESS 1132 - 933 HORNBY ST PAUL: 604.802.1333 VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 778.882.5200			EMAIL verasal@outlook.co	m	

REASON FOR TODAY'S CALL:

replace wax seal. *key with concierge.

DESCRIPTION OF WORK PERFORMED:

I removed the toilet, cleaned the area underneath, and reinstalled with a new wax seal and supply line. During testing I noticed the FillValve was not fully shutting off on some flushes, causing the toilet to run periodically. I replaced the FillValve and tested again.

QIY.	CODE		DESCRIPTION	UNIT PRICE	PRICE
1	7	Replace Toilet Wax Seal - Standard			\$189.00
1	9520164	PRO45B ANTI-SYPH FILL V	LV UQ	\$35.00	\$35.00
0	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$224.00	
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	GST (5%):	\$11.20
				TOTAL:	\$235.20

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY
MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND
MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,
SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES
RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK
CHARGES. E. & O. E.

	2017-06-02		
CUSTOMER SIGNATURE	DATE		