



2017-06-21

HST #837181627

DATE 2017-06-21	TECHNICIAN Darren Mann		JOB/O 7408	RDER #	REFERENCE TEXT Client reference
FIRST NAME Kenneth		LAST NAME Chow			
BILLING ADDRESS COMPANY / BILLING NAME 310 - 638 BROUGHTON ST VANCOUVER, V6G3K3 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 517 - 1055 RICHARDS ST, BUZ# 8343 ROGER: 778-323-4919 778-840-8180 VANCOUVER, V6B 0C2 BRITISH COLUMBIA, CANADA	
PHONE 604.839.7368	-			EMAIL ken@vancouverrentit.com	

REASON FOR TODAY'S CALL:

Shower diverter requires replacement

DESCRIPTION OF WORK PERFORMED:

-During replacement of the tub/shower diverter Spool I noticed that the mixing & pressure balance cartridge was leaking. I replaced the diverter spool and mixing & pressure balance cartridge. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	<i>I</i> .	Replace Danze Diverter Spool and Mixing&Pressure Balance Cartridge	\$199.00	\$199.00
0	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$9.95
			TOTAL:	\$208.95
		We did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,		