

(E) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2017-06-23	TECHNICIAN Darren Mann		JOB/O 7434	RDER #	REFERENCE TEXT Client reference
FIRST NAME Easyrent		LAST NAME Admin	7		
BILLING ADDRESS EASYRENT REAL ESTATE SE 100 - 1290 HOMER ST VANCOUVER, V6B2Y5 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 1402 - 969 RICHARDS ST ROOZBEH: 604.618.0406 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.662.3279				EMAIL info@easyrent.ca	

REASON FOR TODAY'S CALL:

-Replace garburator -Tenant reports water in the kitchen faucet to be too hot. *grab keys from Easyrent

DESCRIPTION OF WORK PERFORMED:

-I replaced the garburator with a new Waste King 1001 and tested. -The hot water in the building is set extremely high. It is not just the kitchen faucet but all fixtures that are supplied with this hot water from the building. Unfortunately there is nothing that can be done within the unit to lower this temperature.

QTY.	CODE		DESCRIPTION			
1		Supply & Install 1/2HP	Naste King 1001 Garburator	\$279.00	\$279.00	
Gwe us Feedback WARRAN			RANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$279.00	
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DA MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, AB		\$13.95	
		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$292.95	
	t tell us how v	M Si R TI	DE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARC TERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE TITLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY C SULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. RMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AN ARGES. E. & O. E.	E FOR BROKEN, DTHER DAMAGES		
			CUSTOMER SIGNATURE	DATE		