

Phone: 604.727.4484 yaletownplumbing.com

HST #837181627

DATE 2017-07-06	TECHNICIAN Darren Mann		JOB/ORDER # 7466	REFERENCE TEXT Client reference	
FIRST NAME AI		LAST NAME Hattori			
BILLING ADDRESS COMPANY / BILLING NAME 705 - 128 WEST CORDOVA ST VANCOUVER, V6B 0E6 BRITISH COLUMBIA, CANADA			BUZZER: PLEASE CA VANCOUVER, V6B 0E	SERVICE ADDRESS  705 - 128 WEST CORDOVA STREET BUZZER: PLEASE CALL VANCOUVER, V6B 0E6 BRITISH COLUMBIA, CANADA	
PHONE 604-727-7971			EMAIL alhattori@hotmail.com	) / l	

## REASON FOR TODAY'S CALL:

In the bathtub (shower is separate), there is no hot water and barely any cold water pressure that comes out the tap. It's a single handle and I've taken off the knob and tried to adjust the little screws for hot and cold. I've tried turning both ways quite a bit and it doesn't do anything other than decrease the water pressure more. The tub hasn't been used much at all, so i can't even remember running the bath in 6+ years. I wonder based on the stuff I've read online if the pipes are now clogged from lack of use. In the bathroom where the tub is, the separate shower works fine, so does the toilet and sink. The kitchen sink has never had a problem

## **DESCRIPTION OF WORK PERFORMED:**

I replaced the cartridge within the shower valve and tested. Pressure is back to normal.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	Ш.,	Replace Single Cartridge - Moen		\$129.00
0		warranty: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$129.00
Gwe us Feedback  Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your invoice and tell us how we did.  Thank You!		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$6.45
		ls from your	TOTAL:	\$135.45
		MATERIALS LISTED HEREON ARE CORRECT, YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BRO	OKEN,	

CUSTOMER SIGNATURE

2017-07-06

DATE