

Phone: 604.727.4484 yaletownplumbing.com

HST #837181627

DATE 2017-07-06	TECHNICIAN Darren Mann		JOB/ORDER # 7467		REFERENCE TEXT Client reference
FIRST NAME Lawrence		LAST NAME Tapley			
BILLING ADDRESS COMPANY / BILLING NAME 408 - 1225 RICHARDS ST VANCOUVER, V6B 1E6 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS 408 - 1225 RICHARDS ST BUZZER: 1408 VANCOUVER, V6B 1E6 BRITISH COLUMBIA, CANADA	
PHONE 604-724-0114				EMAIL lawrencet@knowledge.ca	

REASON FOR TODAY'S CALL:

Shower diverter is broken. Spring popped out of the top. I am able to run water for a bath, but diverting the water to the shower is impossible.

DESCRIPTION OF WORK PERFORMED:

-I replaced the tub spout with a new Delta pull-down type diverter spout. During testing I noticed the shower valve handle was quite stiff to turn on/off. I replaced the cartridge within the valve. I also replaced the shower head and arm.

QTY.	CODE		DESCRIPTION	UNIT PRICE	PRICE
1		Replace Standard Tub Spout Diverter		\$159.00	\$159.00
1		HC44 Cartridge		\$75.00	\$75.00
1		Delta Shower Head & Arm		\$25.00	\$25.00
Please visit our feedback page at: LABOUR - MAINTENA		WARRANTY: PARTS	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	SUBTOTAL:	\$259.00
		LABOU		GST (5%):	\$12.95
		com/reedback [1]		TOTAL:	\$271.95

Thank You!

Fill in the required details from your invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNO MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND T	
MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RES	SPONSIBLE FOR BROKEN,
SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MAT	
CHARGES. E. & O. E.	
	2017-07-06
CUSTOMER SIGNATURE	DATE