



HST #837181627

DATE 2017-07-21	TECHNICIAN Darren Mann		JOB/O 7512	RDER#	REFERENCE TEXT Client reference	
FIRST NAME Christiaan		LAST NAME lacoe	707			
BILLING ADDRESS COMPANY / BILLING NAME 306 - 1208 BIDWELL ST VANCOUVER, V6G2K9 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 306 - 1208 BIDWELL ST, BUZ VANCOUVER, V6G2K9 BRITISH COLUMBIA, CANAD		
PHONE 604.809.3543				EMAIL christiaan.iacoe@gmail.com		

REASON FOR TODAY'S CALL: tub control leaking through handle(Moen)

DESCRIPTION OF WORK PERFORMED:

I replaced the shower valve mixing cartridge in the tub and tested.

QTY.	CODE	DESCRIPTION			PRICE
1		Replace Single Cartridge - Mo	en	\$129.00	\$129.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		warranty:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	SUBTOTAL:	\$129.00
				GST (5%):	\$6.45
		ls from your		TOTAL:	\$135.45

<u> Thank You!</u>

invoice and tell us how we did.

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CHARGES, E. & O. E.

2017-07-21

CUSTOMER SIGNATURE

DATE