

2017-08-23

HST #837181627

DATE 2017-08-23	TECHNICIAN Darren Mann		JOB/ORDER # 7636		REFERENCE TEXT Client reference	
FIRST NAME Donny		LAST NAME Chan	97			
BILLING ADDRESS COMPANY / BILLING NAME 508 - 1055 RICHARDS ST VANCOUVER, V6B0C2 BRITISH COLUMBIA, CANADA		4	SERVICE ADDRESS 508 - 1055 RICHARDS ST, BUZZER 8315 STEFAN TIRSCHLER 604.445.4245 STEFAN.TIRSCHLER@GMAIL.COM VANCOUVER, V6B0C2 BRITISH COLUMBIA, CANADA			
PHONE 604.360.3162				EMAIL chan338@gmail.com		

REASON FOR TODAY'S CALL:

Slow water leak from garbage disposal. It's a slow leak, only happens when water goes down the sink, and looks like it's dripping out of the bottom of the motor unit.

DESCRIPTION OF WORK PERFORMED:

The garburator was leaking straight through the unit, out of the bottom. I replaced the garburator with a new Badger5 and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	/.	Supply & Install 1/2HP Badger5 Garburator	\$319.00	\$319.00
Q.,,,	SUBTOTAL:	\$319.00		
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$15.95
		s from your	TOTAL:	\$334.95
		MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,		