

HST #837181627

DATE 2017-09-05	TECHNICIAN Darren Mann		JOB/ORDER # 7675	REFERENCE TEXT Client reference
FIRST NAME Nicole		LAST NAME Cloudt		
BILLING ADDRESS COMPANY / BILLING NAME 301 - 501 PACIFIC ST VANCOUVER , V6Z 2X6 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 301 - 501 PACIFIC ST JOEL(ARTNER): 1.778.938.6995 VANCOUVER , V6Z 2X6 BRITISH COLUMBIA, CANADA	
PHONE 1.519.777.8781			EMAIL nicolecloudt@gmail.co	m

REASON FOR TODAY'S CALL:

The tub spout is not fully diverting water to the shower head.

DESCRIPTION OF WORK PERFORMED:

-I replaced th	ne tub spout w	vith a new Delta pull-d	lown type div	rerter spout and installed the customer supplied shower head.		
QTY.	CODE	DESCRIPTION			UNIT PRICE	PRICE
1	//	Replace Standard Tub Spout Diverter			\$159.00	\$159.00
Ruse	s G	eedhack	WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$159.00
Gwe us Feedback Please visit our feedback page at:		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		GST (5%):	\$7.95	
www.yaletownplumbing.com/feedback [1] Fill in the required details from your		INTEREST AT		TOTAL:	\$166.95	
Thank You!		INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.				

CUSTOMER SIGNATURE

2017-09-05

DATE