

HST #837181627

DATE 2017-10-03	TECHNICIAN Darren Mann			REFERENCE TEXT Client reference
FIRST NAME Easyrent		LAST NAME Admin		
BILLING ADDRESS EASYRENT REAL ESTATE SERVICES LTD. 100 - 1290 HOMER ST VANCOUVER, V6B2Y5 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 2406 - 928 RICHARDS ST, BUZ#751 STEVEN: 778.318.7293 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.662.3279			EMAIL info@easyrent.ca	

REASON FOR TODAY'S CALL:

Low water pressure in guest bathroom shower. *Ensuite tub very slow to drain.

DESCRIPTION OF WORK PERFORMED:

-I removed a pressure limiter from the guest bathroom shower spray head. -While onsite the tenant mentioned the master bathroom tub was slow to drain. I used the PowerSpin drain snake to remove hair and tested by filling the tub 8? and draining.

r owerspiri drain shake to remove half and tested by filling the tub o: and draining.								
QTY.	CODE	DESCRIPTION			PRICE			
1		DISCOUNT - Powe	rSpin Drain Cleaning	\$119.00	\$119.00			
Q.ma	(1	endlack	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$119.00			
invoice and tell us how we did. Thank You!			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$5.95			
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$124.95			
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.					

CUSTOMER SIGNATURE

DATE