

HST #837181627

DATE 2017-10-11	TECHNICIAN Darren Mann		JOB/O 7819	RDER #	REFERENCE TEXT 17-1295
FIRST NAME Advent		LAST NAME Admin	7		
BILLING ADDRESS ADVENT REAL ESTATE SERV #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA		<u> </u>	4	SERVICE ADDRESS 905 - 1255 SEYMOUR ST DARAH: 778.834.0013 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.736.6478				EMAIL andrea@adventvancouver.com	

REASON FOR TODAY'S CALL:

Kitchen: Hose for faucet has come unattached from below

DESCRIPTION OF WORK PERFORMED:

The spray head detached from the hose and the hose ended up pulling through to the underside of the sink. Luckily most of the water seemed to collect in a glass vase that happened to be directly below. I reattached the spray head to the hose and tested.

QTY. CODE	DESCRIPTION	UNIT PRICE	PRICE
1 Disc	count Labour	\$99.00	\$99.00
Gwe us Feed	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$99.00
Please visit our feedback page	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$4.95
www.yaletownplumbing.com/fe Fill in the required details from		TOTAL:	\$103.95
Thank You!	MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE

DATE