



HST #837181627

DATE 2017-10-25	TECHNICIAN Darren Mann		JOB/ORDER # 7741		REFERENCE TEXT Client reference
FIRST NAME Florence		LAST NAME Chan	97		
BILLING ADDRESS COLDWELL BANKER PREMIE 6272 EAST BOULEVARD VANCOUVER, V6M3V7 BRITISH COLUMBIA, CANADA		9	4	SERVICE ADDRESS 3103 - 535 SMITHE ST VANCOUVER, V6B 0H2 BRITISH COLUMBIA, CANADA	ı.
PHONE 604.782.3830				EMAIL flochan@shaw.ca	

REASON FOR TODAY'S CALL:

-Lotus spray toilet seat removal. Original not present. -The washer hoses also need to be changed. -Plus, according to the home inspector, the dishwasher drain line is at risk of back flow due to being installed too low

DESCRIPTION OF WORK PERFORMED:

-I delivered and installed the new toilet seat. -I replaced the laundry hoses with braided stainless supply hoses. -I suggested having an appliance repairman look at the dishwasher drain hose as it seems to be too short to run any higher.

QTY.	CODE		DESCRIPTION	UNIT PRICE	PRICE
2		Discount Labour		\$99.00	\$198.00
1	11	Caroma Adelaide Seat		\$70.00	\$70.00
2	116	Braided Stainless Laundry Hose	е	\$22.00	\$44.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1]		warranty:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	SUBTOTAL:	\$312.00
				GST (5%):	\$15.60
				TOTAL:	\$327.60

Thank You!

Fill in the required details from your invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKN	
MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT R	
SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUT RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.	
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MA	
CHARGES. E. & O. E.	
	2017-10-25
CLISTOMER SIGNATURE	DATE