

HST #837181627

DATE 2017-12-08	TECHNICIAN Darren Mann		JOB/ORDER # 8000		REFERENCE TEXT
FIRST NAME Erich		LAST NAME Herchen			
BILLING ADDRESS COMPANY / BILLING NAME 502 - 1238 RICHARDS ST VANCOUVER, V6B6M6 BRITISH COLUMBIA, CANADA		- 19	4	SERVICE ADDRESS 502 - 1238 RICHARDS ST, BU VANCOUVER, V6B6M6 BRITISH COLUMBIA, CANADA	
PHONE 604.505.1288				EMAIL erichh3@hotmail.com	

REASON FOR TODAY'S CALL:

Low water pressure in tub/shower.

DESCRIPTION OF WORK PERFORMED:

I first repaired the shower valve integral stops by replacing the washers, stems, packing, and packing nuts. I then flushed the Hot & Cold lines out through the shower valve before installing a new Tempress ii cartridge. *Bits of debris were flushed out of the Hot & Cold lines leading into the shower valve. I left this debris with the

QTY.	CODE		UNIT PRICE	PRICE	
1		Replace Shower Cartridge - Te	\$209.00	\$209.00	
2		Integral Stop Repair	\$25.00	\$50.00	
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	SUBTOTAL:	\$259.00
				GST (5%):	\$12.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$271.95

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2017-12-08

CUSTOMER SIGNATURE

DATE