



DATE 2017-12-19	TECHNICIAN Darren Mann	JOB/ORDER # 8023	REFERENCE TEXT Client reference
FIRST NAME Wiri		LAST NAME Campos	
BILLING ADDRESS COMPANY / BILLING NAME 106 - 2080 MAPLE ST VANCOUVER, V6J4P9 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 106 - 2080 MAPLE ST VANCOUVER, V6J4P9 BRITISH COLUMBIA, CANADA	
PHONE 604.305.0639		EMAIL Wiriamcampos@gmail.com	

REASON FOR TODAY'S CALL:
 The pressure of the water is not working. All water is coming at the bottom


DESCRIPTION OF WORK PERFORMED:
 The tub spout diverter was not functioning. I replaced the tub spout with a new Delta pull-down type diverter spout and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Standard Tub Spout Diverter	\$159.00	\$159.00
SUBTOTAL:				\$159.00
GST (5%):				\$7.95
TOTAL:				\$166.95

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY
LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



 CUSTOMER SIGNATURE

2017-12-19

 DATE