

Phone: 604.727.4484 yaletownplumbing.com

HST #837181627

DATE 2017-12-20	TECHNICIAN Darren Mann		JOB/ORDER # 8033	REFERENCE TEXT Client reference
FIRST NAME Rachel		LAST NAME Friederichsen		
BILLING ADDRESS COMPANY / BILLING NAME 307 - 77 - WALTER HARDWICK AVE VANCOUVER, V5Y 0C6 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 307 - 77 - WALTER HARDWICK AVE BUZZER: 3307 VANCOUVER, V5Y 0C6 BRITISH COLUMBIA, CANADA		
PHONE 604.600.3031			EMAIL rachel.friederichsen	@gmail.com

REASON FOR TODAY'S CALL:

My problem is my kitchen faucet. I?ve had low pressure for a long time now and the building manager tells me it is not a problem of the building but of my faucet. Recently my faucet seems to ?jump? when I opwn it and water leaks out the bottom. Not good! Hoping for some help.

DESCRIPTION OF WORK PERFORMED:

-I replaced 2 orings where the spout of the faucet connects to the faucet base and reattached the spout. -The pressure decrease was caused by the aerator being full of debris. I replaced the aerator and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	//.	Discount Labour	\$99.00	\$99.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$99.00
		k page at: Labour - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE,	, ,	\$4.95
			TOTAL:	\$103.95
		MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSI	BLE FOR BROKEN, IY OTHER DAMAGES	

2017-12-20