



2018-01-26

DATE

HST #837181627

DATE 2018-01-26	TECHNICIAN Darren Mann		JOB/ORDER # 8151	REFERENCE TEXT Client reference	
FIRST NAME Easyrent		LAST NAME Admin			
BILLING ADDRESS EASYRENT REAL ESTATE SE 100 - 1290 HOMER ST VANCOUVER, V6B2Y5 BRITISH COLUMBIA, CANADA			SERVICE ADDR 3001 - 977 MAIN ALY: 604.828.81 VANCOUVER, BRITISH COLUM	LAND ST, BUZ#7266 04	
PHONE 604.662.3279			EMAIL info@easyrent.ca	a	

## REASON FOR TODAY'S CALL:

We are having problems with the temp regulation from our bath/shower tap. It fluctuates from very hot to cold while having a shower.

## DESCRIPTION OF WORK PERFORMED:

I replaced the	e mixing/press	sure balance shower valve cartridge and tested.		
QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace SHWR VLV Cartridge - PBR40	\$199.00	\$199.00
Quive	us F	warranty: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$199.00
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your invoice and tell us how we did.  Thank You!		k page at:  Labour - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF  MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$9.95
			TOTAL:	\$208.95
		WE did.  MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLE DELICEDED DETERORATION OF LEAD RIDES ENTITIES. CLEAN QUITE AND ANY OTHER DAMAGES.		

CUSTOMER SIGNATURE