

HST #837181627

DATE 2018-03-23	TECHNICIAN Darren Mann		JOB/ORDER # 8322	REFERENCE TEXT Client reference
FIRST NAME Cynthia		LAST NAME Ferguson		
BILLING ADDRESS COMPANY / BILLING NAME 501 - 602 CITADEL PARADE VANCOUVER, V6B 1X2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 501 - 602 CITADEL PARADE, BUZZER 8027 VANCOUVER, V6B 1X2 BRITISH COLUMBIA, CANADA		
PHONE 604-360-7009		EMAIL cynthia.ferguson@gr	EMAIL cynthia.ferguson@gmail.com	

REASON FOR TODAY'S CALL:

Hi, My shower diverter needs to be repaired/replaced. Do you do this kind of work? It has always been difficult to lift it and turn it, and now the knob on top has come off and we can't get it back on. Previously we have tried unscrewing the spout in hopes we can replace it but it doesn't unscrew.

DESCRIPTION OF WORK PERFORMED:

I replaced the tub spout with a new Delta pull-down type diverter spout and tested.

QTY.	CODE		UNIT PRICE	PRICE	
1		Replace Standard Tub Sp	ce Standard Tub Spout Diverter		
Please visit our feedback page at: www.yaletownplumbing.com/feedback Fill in the required details from your invoice and tell us how we did. MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYM WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETE		ITY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$159.00	
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO		\$7.95
		ls from your			\$166.95
		we did.			

SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

Thank You!

2018-03-23

CUSTOMER SIGNATURE

DATE