

HST #837181627

DATE 2018-04-05	TECHNICIAN Darren Mann		JOB/ORDER # 8353		REFERENCE TEXT Client reference	
FIRST NAME Jasper		LAST NAME Chiang				
BILLING ADDRESS COMPANY / BILLING NAME 2210 - 1188 RICHARDS ST VANCOUVER, V6B 3E6 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 2210 - 1188 RICHARDS ST NO BUZ VANCOUVER, V6B 3E6 BRITISH COLUMBIA, CANADA		
PHONE 604.441.9838				EMAIL jasperchiang.ca@gmail.com		

REASON FOR TODAY'S CALL:

leaky kitchen faucet and rusty bath tub drain need replacement

DESCRIPTION OF WORK PERFORMED:

-The kitchen faucet was leaking from the spray hose. Jasper decided to replace the faucet rather than wait for a replacement hose to be shipped from the manufacturer. I installed the customer supplied kitchen faucet and tested. -I installed a new push style tub drain.

QTY.	CODE		UNIT PRICE	PRICE	
1		Replace Standard Tub Spout Diverter			\$159.00
1		Install Customer Supplied Kitch	\$50.00	\$50.00	
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		warranty:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	SUBTOTAL:	\$209.00
				GST (5%):	\$10.45
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$219.45

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CHARGES. E. & O. E.

2018-04-05

CUSTOMER SIGNATURE

DATE