

2018-05-09

HST #837181627

DATE 2018-05-09	TECHNICIAN Darren Mann			REFERENCE TEXT Client reference				
FIRST NAME Colin		LAST NAME Doig						
BILLING ADDRESS RE/MAX CREST REALTY WESTSIDE 1428 WEST 7TH AVE VANCOUVER, V6H1C1 BRITISH COLUMBIA, CANADA			1354 WEST 8TH BRENDA: 403 47 VANCOUVER,	SERVICE ADDRESS 1354 WEST 8TH AVE BRENDA: 403 479-2884JEFF: 403 479-2885 VANCOUVER, BRITISH COLUMBIA, CANADA				
PHONE 604.417.9003			EMAIL colin@colindoig.co	om				

REASON FOR TODAY'S CALL: shower leaking to floor below

DESCRIPTION OF WORK PERFORMED:

I cut access holes in the drywall behind the shower valve. Water is leaking from a soldered connection between the tub spout and rough in valve, and there is also leaking coming from the piping that leads from the top of the rough in valve to the shower head. The wall will have to be opened up and the entire rough in will have to be redone.

QTY.	CODE		UNIT PRICE	PRICE	
1	1.	Discount Labour		\$99.00	\$99.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		and and	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$99.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$4.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$103.95
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE