



HST #837181627

DATE 2018-05-29	TECHNICIAN Darren Mann		JOB/ORDER # 8509		REFERENCE TEXT 18-0677
FIRST NAME Advent		LAST NAME Admin	9/		
BILLING ADDRESS ADVENT REAL ESTATE SERV #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS 706 - 1001 RICHARDS ST BUZ MEAGAN: 604.612.1027 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.736.6478				EMAIL andrea@adventvancouver.com	

REASON FOR TODAY'S CALL:

Both Lav faucets have low water pressure. Garburator leaking.

DESCRIPTION OF WORK PERFORMED:

-The garburator was leaking from cracks in the housing. I replaced the garburator with a new Badger5 and tested by filling and draining the sink multiple times while running the garburator. -I replaced the aerators in both lavatory faucets and tested by filling and draining the sinks multiple times.

QII.	CODE		DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Badgers	5 Garburator	\$329.00	\$329.00
2	11	Aerator 1.5GPM		\$10.00	\$20.00
Please visit our feedback page at:		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	SUBTOTAL:	\$349.00
				GST (5%):	\$17.45
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$366.45

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWN MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.	THAT CHARGES AND SPONSIBLE FOR BROKEN,
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MA	TERIALS AND TRUCK
CHARGES. E. & O. E.	
	2018-05-29
CUSTOMER SIGNATURE	DATE