



2018-06-08

DATE

HST #837181627

DATE 2018-06-08	TECHNICIAN Darren Mann		JOB/ORDER # 8518	REFERENCE TEXT Client reference	
FIRST NAME Melissa		LAST NAME Mackenzie			
BILLING ADDRESS COMPANY / BILLING NAME 204 - 1640 WEST 11TH AVE VANCOUVER, V6J 2B9 BRITISH COLUMBIA, CANADA		9	SERVICE ADDR 204 - 1640 WES VANCOUVER, N BRITISH COLUI	T 11TH AVE, BUZZER #304 /6J 2B9	
PHONE 604.340.8384			EMAIL meliss.mackenz	e@gmail.com	

## REASON FOR TODAY'S CALL:

Delete garb and properly support undermount kitchen sink.

## DESCRIPTION OF WORK PERFORMED:

I first re-siliconed the undermount kitchen sink and secured using L-brackets. I then removed the garburator, installed a basket strainer in it?s place, and repiped the

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Quoted Price	\$239.00	\$239.00
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your invoice and tell us how we did.  Thank Youl		WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$239.00
		k page at:  LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF  MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$11.95
			TOTAL:	\$250.95
		We did.  MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND  MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,  SETTLED PLETED DETERIORATION OF LEAD PIPES SIXTURES CLEAN OUTS AND ANY OTHER DAMAGES.		

CUSTOMER SIGNATURE