



HST #837181627

DATE 2018-07-03	TECHNICIAN Darren Mann		JOB/ORDER # 8635	REFERENCE TEXT	
FIRST NAME Kathy		LAST NAME Gallagher			
BILLING ADDRESS COMPANY / BILLING NAME #2701 - 1500 HORNBY ST BUZ#3132 VANCOUVER, V6Z-2R1 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS #2701 - 1500 HORNBY ST BUZ#3132 VANCOUVER, V6Z-2R1 BRITISH COLUMBIA, CANADA		
PHONE 604.683.1488			EMAIL kmikegallagher@aol.c	EMAIL kmikegallagher@aol.com	

REASON FOR TODAY'S CALL:

Running toilet master ensuite bathroom.

DESCRIPTION OF WORK PERFORMED:

The fillvalve was not fully shutting off when the tank was full and the styrofoam float was detaching from the underside of the flapper. I purchased a Kohler 84499 conversion kit and replaced the toilet fillvalve, flapper, and supply line. Tested and in good working order.

QTY.	CODE		DESCRIPTION			PRICE
1		Replace Fill-Valve Flapper Supply - Kohler 84499			\$309.00	\$309.00
invoice and tell us how we did.		ARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$309.00	
		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO		GST (5%):	\$15.45	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		TOTAL:	\$324.45
		we did.	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREAN ARE CORRECT, VALETOWALD LIMBING IS NOT DESCRIBED.			

Thank You!

SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2018-07-03

CUSTOMER SIGNATURE

DATE