

HST #837181627

DATE 2018-07-19	TECHNICIAN Darren Mann		JOB/ORDER # 8666		REFERENCE TEXT
FIRST NAME Mary		LAST NAME Baldwin	97		
BILLING ADDRESS  1602 - 989 BEATTY ST VANCOUVER, V6Z 3C2 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS  1602 - 989 BEATTY ST, BUZZIVANCOUVER, V6Z 3C2 BRITISH COLUMBIA, CANADA	
PHONE 1.206.335.9806				EMAIL Mmbaldwin@quidnunc.net	

REASON FOR TODAY'S CALL: delete garburator.

## **DESCRIPTION OF WORK PERFORMED:**

-I removed the garburator, installed a basket strainer in it?s place, and repiped the ABS drainage. Tested by filling and draining the sink multiple times. -While onsite I was asked to take a look at the toilet as it seemed to take a few flushes to clear on occasion. I tested the toilet and aside from it taking a little longer to refill after each flush it seemed to be in good working order.

QTY.	CODE	DESCRIPTION				PRICE
1		Delete Garburator & Re-Pipe ABS Drainage				\$219.00
Gwe us Feedback  Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$219.00	
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$10.95	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$229.95	
Fill in the required details from your invoice and tell us how we did.						THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND

<u> Thank You!</u>

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

CUSTOMER SIGNATURE

DATE