

(B) @SimplyPlumbing | | YaletownPlumbing

HST #837181627

DATE 2018-07-26	TECHNICIAN Darren Mann		JOB/ORDER # 8699		REFERENCE TEXT				
FIRST NAME Anoosh		LAST NAME Hafezi							
BILLING ADDRESS				SERVICE ADDRESS					
3501- 1211 MELVILLE ST VANCOUVER, V6E0A7 BRITISH COLUMBIA, CANADA				3501 - 1211 MELVILLE STREE BUZZER#3501 VANCOUVER, V6E0A7 BRITISH COLUMBIA, CANADA					
PHONE 6045626626				EMAIL ahafezi@gmail.com					

## REASON FOR TODAY'S CALL:

Hello, my garburator has stopped working with little or no sign of life. I need it to be repaired or replaced.

## DESCRIPTION OF WORK PERFORMED:

The garburator was cracked and could not be repaired. I replaced the garburator with a new Waste King 1001 and tested by filling and draining the sink while running

QTY.	CODE		UNIT PRICE	PRICE	
1		Supply & Install 1/2HP Was	\$279.00	\$279.00	
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY					\$279.00
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$13.95
		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$292.95
invoice and	nk You	We did.  MADE T MATERI MATERI SETTLE RESULT TERMS:	ST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY HAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND ALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, D., RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES ING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK IS. E. & O. E.		

CUSTOMER SIGNATURE

DATE