

(B) @SimplyPlumbing | YaletownPlumbing

HST #837181627

DATE 2018-08-02	TECHNICIAN Darren Mann		JOB/ORDER # 8713		REFERENCE TEXT			
FIRST NAME Veronica		LAST NAME Thomas						
BILLING ADDRESS			//,	SERVICE ADDRESS				
103 - 125 MILROSS AVE VANCOUVER, V6A0A1 BRITISH COLUMBIA, CANADA				103 - 125 MILROSS AVE, BUZZER 0103 CARLIN(TENANT): 778.288.4048 VANCOUVER, V6A0A1 BRITISH COLUMBIA, CANADA				
PHONE 778.709.1098				EMAIL vrncthms@gmail.com				

REASON FOR TODAY'S CALL:

We have a broken down garburator. We want to remove it and replace it with standard piping.

DESCRIPTION OF WORK PERFORMED:

I removed the garburator, installed a basket strainer in it?s place, and repiped the ABS drainage. I also replaced the basket strainer in the left sink to match the new one in the right. Tested by filling and draining both sides of the sink multiple times.

QTY.	CODE	DESCRIPTION		UNIT PRICE	PRICE
1		Delete Garburator & Re-Pipe ABS Drainage			\$219.00
1	11	Replace Second Basket Strainer		\$35.00	\$35.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	SUBTOTAL:	\$254.00
				GST (5%):	\$12.70
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$266.70

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOW MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THMATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESSETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS A RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.	AT CHARGES AND PONSIBLE FOR BROKEN,
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATE	RIALS AND TRUCK
CHARGES. E. & O. E.	
	2018-08-02
CUSTOMER SIGNATURE	DATE