



DATE 2018-08-23	TECHNICIAN Darren Mann	JOB/ORDER # 8810	REFERENCE TEXT Client reference
FIRST NAME jessica	LAST NAME zhan		
BILLING ADDRESS COMPANY / BILLING NAME 706 - 1833 CROWE ST VANCOUVER, V5Y 0A2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 706 - 1833 CROWE ST, BUZZER N/A VANCOUVER, V5Y 0A2 BRITISH COLUMBIA, CANADA	
PHONE 778.861.3558		EMAIL jessicazhan@hotmail.com	

REASON FOR TODAY'S CALL:  
Leaking from shower adaptor.

DESCRIPTION OF WORK PERFORMED:  
The inline shower filter housing was broken. I installed a new one that the homeowner provided. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00
SUBTOTAL:				\$109.00
GST (5%):				\$5.45
TOTAL:				\$114.45

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2018-08-23

CUSTOMER SIGNATURE

DATE