

(B) @SimplyPlumbing | YaletownPlumbing



HST #837181627

DATE 2018-08-31	TECHNICIAN Darren Mann		JOB/ORDER # 8824		REFERENCE TEXT Client reference
FIRST NAME Nigel		LAST NAME Malkin			
BILLING ADDRESS COMPANY / BILLING NAME 2505 - 638 BEACH CR VANCOUVER, V6Z3H4 BRITISH COLUMBIA, CANADA		9	4	SERVICE ADDRESS 2505 - 638 BEACH CR, BUZZEI CONCIERGE WILL GRANT AC VANCOUVER, V6Z3H4 BRITISH COLUMBIA, CANADA	CESS.
PHONE 604-783-4360				EMAIL nigelcmalkin+1@gmail.com	

REASON FOR TODAY'S CALL: Running toilet. *Caroma

DESCRIPTION OF WORK PERFORMED:

The toilet fillvalve would not stop running, even when the tank was full. Also the flushvalve gasket was warped. I replaced the toilet fillvalve, flushvalve gasket, and supply line. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Toilet FillValve, Flapper, Supply - Standard	\$169.00	\$169.00
<i>Q.</i>	Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$8.45
		s from your	TOTAL:	\$177.45
		INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY WE did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED PLISTED DETERIORATION OF LEAD PIDES. SIXTURES CLEAN OUTS AND ANY OTHER DAMAGES.		

CUSTOMER SIGNATURE

DATE