





HST #837181627

DATE 2018-09-05	TECHNICIAN Darren Mann		JOB/OF 8814	RDER #	REFERENCE TEXT Client reference
FIRST NAME Rachel		LAST NAME Morisette			
BILLING ADDRESS COMPANY / BILLING NAME 204 - 1924 COMOX ST VANCOUVER, V6G 1R4 BRITISH COLUMBIA, CANADA		19	4	SERVICE ADDRESS 204 - 1924 COMOX ST VANCOUVER, V6G 1R4 BRITISH COLUMBIA, CANADA	
PHONE 604.244.3292				EMAIL steverachel@gmail.com	

REASON FOR TODAY'S CALL: leak under kitchen sink.

DESCRIPTION OF WORK PERFORMED:

The ABS drainage under the sink was broken in 2 places. I repiped the ABS drainage and tested by filling and draining both sides of the sink multiple times.

QTY.	CODE		UNIT PRICE	PRICE		
1		Re-Pipe ABS Drainag	Pipe ABS Drainage - DOUBLE KITCHEN SINK			
Q.mo	(1	endlack w	RANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$169.00	
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your			<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUT	GST (5%):	\$8.45	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$177.45	
invoice and tell us how we did.			TEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS ADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AN	ID		

Thank You!

MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES, E. & O. E.

CUSTOMER SIGNATURE

2018-09-05

DATE