



DATE 2018-09-06	TECHNICIAN Darren Mann	JOB/ORDER # 8841	REFERENCE TEXT
FIRST NAME Rosemary	LAST NAME Shih		
BILLING ADDRESS COMPANY / BILLING NAME 5962 CHANCELLOR BLVD VANCOUVER, V6T 0A1 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 5962 CHANCELLOR BLVD VANCOUVER, V6T 0A1 BRITISH COLUMBIA, CANADA	
PHONE 604.813.3331		EMAIL Rosemaryshih@yahoo.ca	

REASON FOR TODAY'S CALL:

-Running toilet in guest bathroom on second floor. -Water trickling down the inside of bowl after flushing in master ensuite toilet(repaired 3 months prior).

DESCRIPTION OF WORK PERFORMED:

-I replaced the FillValve and supply line in the guest bathroom toilet on the second floor. -The water trickling down the back of the inside of the bowl after a flush happens in all of the toilets. I believe this water to be the residual water draining out from within the bowl rim because it eventually stops after 5-10 minutes.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace toilet FillValve - standard	\$159.00	\$159.00


Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL: \$159.00
 GST (5%): \$7.95
 TOTAL: \$166.95



2018-09-06

CUSTOMER SIGNATUREDATE