

(a) @SimplyPlumbing f YaletownPlumbing

## HST #837181627

DATE 2018-09-12	TECHNICIAN Darren Mann		JOB/O 8850	RDER #	REFERENCE TEXT Client reference
FIRST NAME Lindsay		LAST NAME Keele	7		
BILLING ADDRESS COMPANY / BILLING NAME 201 - 2008 BAYSWATER ST VANCOUVER, V6K 4A8 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 201 - 2008 BAYSWATER ST, B MIKE(HUSBAND): 604.725.490 VANCOUVER, V6K 4A8 BRITISH COLUMBIA, CANADA	0
PHONE 604.354.2236				EMAIL lindsaykeele@gmail.com	

REASON FOR TODAY'S CALL: Leak under bathroom sink.

## DESCRIPTION OF WORK PERFORMED:

The leak was coming from where the lever arm attaches to the mechanical drain assembly. The nut that secures the lever arm was loose. I tightened this connection and during testing noticed the drain was backing up. I cleared hair from the top of the drain assembly and tested by filling and draining the sink multiple times. There are no other signs of leaking and the drain is now flowing freely.

QTY. CODE	DESCRIPTION	UNIT PRICE	PRICE
1 La	abour	\$109.00	\$109.00
Gwe us Fee	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$109.00
Please visit our feedback pa	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$5.45
www.yaletownplumbing.com Fill in the required details fro		TOTAL:	\$114.45
invoice and tell us how we d	MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,		