

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2018-10-01	TECHNICIAN Darren Mann		JOB/ORDER # 8903		REFERENCE TEXT 18-1331	
FIRST NAME Advent		LAST NAME Admin	7			
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 1312 - 610 GRANVILLE ST, BUZ5146 ALVI: 778.386.4801 VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 604.736.6478				EMAIL andrea@adventvancouver.com		

REASON FOR TODAY'S CALL: Garburator not working.

DESCRIPTION OF WORK PERFORMED:

I was able to free up the garburator but found the swing arms to be seized up, and there was also cracks in the housing. I replaced the garburator with new and tested by filling and draining both sides of the sink while running the garburator.

QTY.	CODE			DESCRIPTION	UNIT PRICE	PRICE	
1		Supply & Install 1/2	Supply & Install 1/2HP Waste King 1001 Garburator				\$279.00
Gwe us Feedback Please visit our feedback page at:		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$279.00		
		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO			GST (5%):	\$13.95	
www.yaletownplumbing.com/feedback [1] Fill in the required details from your	INTEREST A	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$292.95			
invoice and tell us how we did. <u>Thank You!</u>		MATERIALS SETTLED, R RESULTING	I SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED A S LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NO SUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN (B FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPI T CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR E. & O. E.	OT RESPONSIBLE FOR BROKEN, OUTS AND ANY OTHER DAMAGES ING.			
				CUSTOMER SIGNATURE	DATE		